GOVERNMENT OF THE DISTRICT OF COLUMBIA

Department of Energy and Environment Lead-Safe and Healthy Housing Division | Lead Compliance and Enforcement Branch

CLEARANCE EXAMINATION AND REPORT REQUIREMENTS

LEAD-BASED PAINT HAZARD ABATEMENT 20 DCMR § 3316						
3316.10	Except when an entire building has been razed, the issuance of an abatement permit pursuant to §3316.4 triggers a requirement that the individual or business entity to whom the permit was issued submit to DOEE a clearance report no later than seven (7) business days after completion of the permit-related activities, to close out the permit, as follows:					
		(a) A clearance examination shall be performed no sooner than one (1) hour and no later than three (3) busines days after the completion of the abatement activities, and shall be repeated until the clearance examination is passed and a clearance report is issued;				
		(b) The clearance examination may be performed by a risk assessor or by a lead-based paint inspector , unless DOEE has required that the clearance examination be performed by a risk assessor;				
		(c) In the case of work that occurs on a floor in a multifamily property that also contains an occupied unit, the clearance examination shall consist of:				
		(1) A visual inspection of the common area on each such floor to confirm that no visible paint debris is present between the front door of each unit where such work is undertaken and the entry door of any occupied unit on such floor; and				
		(2) Dust sampling in the common area on each such floor, within two feet (2 ft.) from the entry door of each unit where such work is undertaken, and within two feet (2 ft.) from the entry door of either all occupied units on such floor, or at least three (3) of the occupied units, whichever is fewer, provided that the risk assessor selects those units most likely to have been affected by dust migration resulting from the work;				
		(d) Notice to DOEE that a dust test will be performed shall be provided whenever the dust test is related to a clearance examination resulting from an Order to Eliminate Lead-Based Paint Hazards, and shall be provided to DOEE by fax, in person, or via the DOEE website, on a DOEE-specified form, submitted to DOEE at least twenty-four (24) hours prior to conducting the dust test, or as soon as practicable, whichever is sooner;				
		(e) Each environmental sample taken during a clearance examination shall be analyzed by an appropriately accredited lab, and the total samples submitted to the lab shall include as a quality assurance measure one (1) blank sample for lab analysis for each permit issued pursuant to § 3316.4; and				
		(f) No other raze or demolition activity shall be undertaken at the property in question until a clearance report has been issued and submitted to DOEE, except that demolition activities on floors where no occupied units are located may continue in the interim.				





3316.11	The issuance of an abatement permit in all cases other than a permit issued pursuant to §3316.4					
	triggers a requirement that the individual or business entity to whom the permit was issued submit to DOEE a					
	clearance report no later than seven (7) business days after completion of the abatement activities, to close					
	out the permit, as follows:					
		(a) A clearance examination shall be performed no sooner than one (1) hour and no later than three (3) business days after the completion of the abatement activities, and shall be repeated until the clearance examination is passed and a clearance report is issued;				
		(b) If there is no Order to Eliminate Lead-Based Paint Hazards, the clearance examination may be performed by a dust sampling technician, a lead-based paint inspector, or by a risk assessor, whether or not employed by the owner;				
		(c) If there is no Order to Eliminate Lead-Based Paint Hazards, the clearance examination shall consist of:				
		(1) A visual inspection of each work area, to ensure paint is in intact condition;				
			(2) A visual inspection of each work area,	to ensure there is no visible dust or debris ;		
			(3) Dust sampling in each room that conta	ins a work area, on the following surfaces in each sampled room:		
			\square (A) One (1) floor sample; and			
			\square (B) For rooms that contain a window	, one (1) window sill or one (1) window well sample;		
		(4) Whenever a work area is located on the exterior of a property, and whenever a work area involves a window or a door that opens to the exterior of a property, a dust sample on any concrete or other rough exterior horizontal surface within the work area(s); and				
		(5) Soil sampling if any abatement activity included lead-contaminated bare soil remediation, or if exterior work to eliminate a lead-based paint hazard was performed within ten feet (10 ft.) of a bare soil area, provided such sampling occurs on the same property;				
		(d) Each environmental sample taken during a clearance examination shall be analyzed by an appropriately accredited lab and shall include as a quality assurance measure one (1) blank sample for lab analysis for each unit or property subject to the clearance examination, or in the case of a clearance examination that spans more than one (1) day, one (1) blank sample for lab analysis per day for each property subject to the clearance examination; and				
		(e) Each clearance report shall contain a copy of the current DOEE-issued certification card belonging to the individual that conducted the clearance examination and the date the clearance report was issued.				
MAKE SURE YOUR CLEARANCE REPORT INCLUDES THE FOLLOWING:						
1 Proports	2445	200 22		7. Name and address of each firm and supervisor involved		
Property address and specific units or Name address simple and District			nature, and District of Columbia	in lead-hazard reduction activity		
		_	er of each person involved in the	8. Start and completion date of the lead hazard reduction		
clearan			•	activity		
3. Name and identification number of each laboratory conducting the analysis				Detailed written description of the lead hazard reduction activity including the methods used		
4. Date of clearance examination 10. Location of exterior surfaces, interior rooms, c						
5. Results of the visual assessment for the presence of deteriorated paint and visible dust, debris, residue, or				areas and/or component where the hazard reduction occurred		

paint chips

6. Result of the analysis of dust samples in micrograms per

square foot $(\mu g/ft^2)$ by location of samples

11. Indicate if the unit passed or failed

12. Any recommended monitoring requirement